

# MARUTI SUZUKI SWIFT - 2 AIRBAGS



7.08 max. 17.00 Adult



16.23 max. 49.00 Child

Tested at 64 km/h

Bodyshell integrity: UNSTABLE

## ADULT OCCUPANT PROTECTION



FRONT PASSENGER

DRIVER

## CAR DETAILS

**TESTED MODEL** MARUTI SUZUKI SWIFT, RHD

**BODY TYPE** 5 DOOR HATCHBACK

**CRASH TEST WEIGHT** KG 1079

**YEAR OF PUBLICATION** 2018

## CHILD RESTRAINTS

	CHILD RESTRAINT	HEAD / CHEST	CRS TYPE	ADJUST	POSITION
18 MONTH OLD CHILD	BRITAX DUO PLUS	POOR / POOR	1	ISOFIX/TT	FWF
3 YEAR OLD CHILD	BRITAX DUO PLUS	PROTECTED / VULNERABLE	1	ISOFIX/TT	FWF

## SAFETY EQUIPMENT

FRONT SEATBELT PRETENSIONERS	YES	SIDE BODY AIRBAGS	NO	SBR	NO
DRIVER FRONTAL AIRBAG	YES	SIDE HEAD AIRBAGS	NO	ISOFIX ANCHORAGES	YES
FRONT PASSENGER FRONTAL AIRBAG	YES	DRIVER KNEE AIRBAG	NO	ABS (4 CHANNEL)	YES

### ADULT OCCUPANT

The protection offered to the driver and passenger head and neck was good. Driver chest showed weak protection while passenger chest showed adequate protection. Driver's knees showed marginal protection and passengers' knees good and adequate protection as they could impact with dangerous structures behind the dashboard supported by the Transfasciatube. The bodyshell was rated as unstable and it was not capable of withstanding further loadings. The car offers standard SBR for driver but it does not meet the minimum requirements.

### CHILD OCCUPANT

The child seat for the 3 year old was installed FWF with ISOFIX and top tether and was able to prevent excessive forward movement during the impact while it offered good protection and marginal protection to the chest. The 18 month old CRs was installed with ISOFIX and top tether forward facing which explains the loss of head points, it showed poor protection for the head and chest. The recommended CRSs did not show incompatibility. The vehicle offers standard ISOFIX and top tether anchorages in the 2 outboard rear seats and does not offer 3 point belts in all seating positions.