

#SAFERCARSFORINDIA

Maruti Suzuki IGNIS












SPECIFICATIONS

Tested model	Maruti Suzuki Ignis
Body type	5 door hatchback - sedan
Year of publication	2022
Crash test weight (KG)	1092
VIN from which Rating applies	
Made in	India
Test valid for	India market

SAFETY EQUIPMENT

DRIVER	PASSENGER	REAR		
YES - STANDARD	YES - STANDARD	NOT APPLICABLE		
YES - STANDARD	YES - STANDARD	NOT AVAILABLE		
YES - STANDARD	YES - STANDARD	NOT AVAILABLE		
NOT AVAILABLE	NOT AVAILABLE	NOT APPLICABLE		
NOT AVAILABLE	NOT AVAILABLE	NOT AVAILABLE		
NOT AVAILABLE	NOT AVAILABLE	NOT AVAILABLE		
NOT AVAILABLE	NOT AVAILABLE	NOT AVAILABLE		
NOT AVAILABLE	NOT AVAILABLE	NOT AVAILABLE		
NOT APPLICABLE	NOT AVAILABLE	YES OUTBOARD SEAT		
NOT APPLICABLE	NOT AVAILABLE	NO		
NOT APPLICABLE	NO	NOT APPLICABLE		
YES - STANDARD	YES - STANDARD	NOT AVAILABLE		
NOT AVAILABLE				
NO	NO			
NOT AVAILABLE				
NOT AVAILABLE	NOT AVAILABLE			
NOT AVAILABLE				
NOT AVAILABLE				
	YES - STANDARD YES - STANDARD NOT AVAILABLE NOT AVAILABLE NOT AVAILABLE NOT AVAILABLE NOT APPLICABLE	YES - STANDARD YES - STANDARD YES - STANDARD YES - STANDARD NOT AVAILABLE NOT AVAILABLE NOT AVAILABLE NOT AVAILABLE NOT AVAILABLE NOT AVAILABLE NOT AVAILABLE NOT AVAILABLE NOT AVAILABLE NOT AVAILABLE NOT AVAILABLE NOT AVAILABLE NOT APPLICABLE NOT AVAILABLE NOT APPLICABLE NOT AVAILABLE NOT APPLICABLE NO YES - STANDARD YES - STANDARD NOT AVAILABLE NO NOT AVAILABLE NO NOT AVAILABLE NO NOT AVAILABLE NO NOT AVAILABLE		

ADULT OCCUPANT PROTECTION



Comments

Frontal impact: The protection offered to the driver's and passenger's head and neck was good. Driver's chest showed weak protection and passenger's chest showed adequate protection. Driver's and passenger's knees showed marginal protection as they can impact with dangerous structures behind the fascia. Driver's tibias showed adequate protection and passenger's tibias showed good protection. Footwell area was rated as stable. The bodyshell was rated as unstable and it will not be capable of withstanding further loadings.

Side impact: head protection was weak and chest protection was poor. Abdomen protection was adequate and pelvis protection was good. Door opening modifier was applied due to risk of ejection of rear occupants.

Side pole impact: was not performed as the car does not have side head protection even as optional.

SBR: the car offers SBR for both front occupants.

FSC: not available.

CHILD OCCUPANT PROTECTION

CHILD RESTRAINT SYSTEM

Dynamic score 0.00 (max 24.00)

CRS Installation Score 3.86 (max 12.00)

Vehicle assessment score

0.00 (max 13.00)

	Child restraint	Dynamic score	CRS Type	Adjust	Position
18 month old child	Maxi Cosi CabrioFix with FamilyFix Base	Front 0.00 (8 max) Side 0.00 (4 max)	0+	ISOFIX/LEG	RWF
3 year old child	Maxi Cosi Pearl with FamilyFix Base	Front 0.00 (8 max) Side 0.00 (4 max)	I	ISOFIX/LEG	FWF

	Front Passenger	2nd row outboard	2nd row centre
ISOFIX	NOT AVAILABLE	YES - STANDARD	NOT AVAILABLE
i-Size	NOT AVAILABLE	YES - STANDARD	NOT AVAILABLE
Integrated CRS	NOT AVAILABLE	NOT AVAILABLE	NOT AVAILABLE

CRS INSTALLATION ASSESSMENT

■ PASS ■ FAIL ■ EXEMPT

		1ST ROW	2ND ROW		
REFERENCE LIST		LEFT	LEFT CENTER RIGHT		
Group 0+	Peg Perego Viaggio Switchable (BELTED)	0		•	
Group 0+	Roemer Baby Safe (ISOFIX / LEG)	0	N/A	N/A	N/A
Group 0+	Bébé Confort Stry Fix / Maxi Cosi Citi (BELTED)	0	•	•	•
Group I	Peg Perego Viaggio Switchable FWF (BELTED)	0	•	•	•
Group I	Graco Cadeira Nautilus FWF (BELTED)	0	•	•	•
Group II/III	Cybex Solution M-Fix (BELTED)	0	•	•	•
Group II/III	Graco Cadeira Nautilus (BELTED)	0	•	•	•
MANUFACTURTER					
Q1.5	Maxi Cosi CabrioFix with FamilyFix Base (ISOFIX / LEG)	0	•	N/A	•
Q3	Maxi Cosi Pearl with FamilyFix Base (ISOFIX / LEG)	0	•	N/A	•

Comments

Frontal impact: the manfacturer refused to recomend CRS for the test therefore dynamic points were not awarded. The child seat for the 3 year old was installed forward facing using the ISOFIX anchorages and a support leg and it was able to prevent head exposure during the frontal impact. The child seat for the 18 month old was installed rearward facing using the ISOFIX anchorages and a support leg and it was able to prevent head exposure during the frontal impact offering good protection.

Side impact: both CRS's offered full side impact protection.

The car does not offer 3 point belts in all seating positions. ISOFIX and top tether anchorages are standard in the 2 outboard rear seats. It does not offer the possibility to disconnect the frontal passenger airbag in case a rearward facing CRS will be installed in this position. The CRS installation passed only for some of the assessed CRS.